

Report ID: 19,627,601 Version: 1 05 Aug 2019 Created:

Make:	Toyota	Model:	Rav4	Body Style:	Wagon		Pass	Fail	N/A
Year:	1995	Registration:	BNF692	Reg Expiry:	30 Sep 2019	Engine		r	
WoF Expiry:	12 Aug 2019	Odometer:	290,182 Kms	Good No:	19627601	Oil level	~		
VIN:	7A8H61X0703001069	Next Service:	248000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged to	or an additional c	narge.	Coolant condition	~		
	S D R PT W		SDRPT SDRP		S D R PT	Performance	~		
Key:	13DAT IN	=		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	scw			210	HIL SW	Operation		~	
PT = paint defe	ect NP				101h	Noise	~		
C = crack					D PT SC	Clutch			~
P = pin dent	SRPTSC DE				74116	CV joints	~		
* = decals		10		10	ED SPT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SDR W SDRPT W SDRPT W SDPT						Performance		~	
Body Insr	ection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Front bumper held on with cable ties						Tyres (lowest observed tread depth of tyres)			
Front left indicator smashed						Left front 3 mm			mm
						Right front	4	4	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear			mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Driver door cant open from inside handle						Suspension performance	~		
Left front window only works from master switch Engine oil leak						Steering performance	V		
Front outer cv boots leaking grease						Shock absorbers	V		
Underbody rust Brakes worn						Air Conditioning / Heater	I		
	1					Operation	~		
Interior Comments						Electrical / Accessories			
Seats	front left s	eat hole, driver s	eat worn			Head lights	~		
	driver mat	holes				Tail lights	~		
Carpets						Indicators	~		
Panels	door hand	lle surrounds cra	cked			Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
Differential noisy						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
								1	1
Inspected by: John Lindsay Date: 05 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: