

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments Front wheel drive

Dry

		Air Conditioning / He	Air Conditioning / Heater		
		Operation	~		Τ
Interior Comments		Electrical / Accessories			
Seats	Good	Head lights	~	Τ	Τ
Carpets	Floor mats missing	Tail lights	~		
		Indicators	~		
Panels	Average	Dashboard warning I	ights	~	T
Dashboard	Good	Wipers (front & rear)	~		
		Window winder FL	~		
		Window winder FR	~		
General Comments Front hubs noisy when selecting drive to reverse Brake warning light on dashboard		Window winder RL	~		
		Window winder RR	~		
		Bear view mirrors	~		1

Remote locking **Engine Timing Mechanism:** Cambelt Sat. Nav. (basic test only) Evidence of Cam Belt Replacement: Kms: No Reversing camera 06 Aug 2019 Inspected by: Ca Thach Date:

Wet

I have read and understood this condition guide.

Road Conditions During Test Drive:

Name:

Signature:

N/A

V

mm

mm

mm

mm

4.5

V

V

~

V

~

2 V

V

V

V

Yes

Right rear

Suspension

Suspension performance

Steering performance

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Shock absorbers

Spare