

Report ID: 19,629,880 Version: 1 07 Aug 2019 Created:

Make:	Holden	Model:	Astra	Body Style:	Sedan		Pass	Fail	N/A
Year:	2003	Registration:	BGF843	Reg Expiry:	14 Aug 2019	Engine			
	2005 27 May 2020	Odometer:	211,873 Kms	Good No:	19629880	Oil level		~	
VIN:	W0L0TGF6935139796			Service History		Smoke & fumes	~	•	
					,	Performance	~		
	port is not a warranty		6	Danta harra mat		Noise	~		
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	/endor recommends	Cooling System	•		L
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	S PT P	-0	SDW SD		S D	Radiator / Hoses (visual)	~		
S = scratch	STE	AU			The second se	Transmission	•		I
D = dent	D PT SC W			The	S PT W	Operation	~		
R = rust PT = paint def				r In	THA	Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals	PT SC PIE			The	ELT SPT	Wheel bearings	~		
SC = stone chi		20		1al	& <u> </u>	Brakes	•		L
W = significant scuffs SD W SPT W SPT W SD						Performance	~		
		Note: son	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
	pection Comments	1010.3011		indy not be disp	ayea in the diagram		-	oftyre	25)
Aerial broken Right rear taillight cracked					Tyres (lowest observed tread depth of tyres)			mm	
	nield mine rust					Right front		5	
						Left rear		5	mm
			_					5	mm
Conditions During Body Inspection: Dry					Right rear		5	mm	
Under Carriage & Under Bonnet Inspection Comments					Spare Yes				
Radio need	-	meemspeede	<u>eominents</u>			Suspension			
Roof lining						Suspension performance	~		
Left front w Oil low	rindow takes a few goes	before it works	from master switch			Steering performance	~		
Remote no	t working					Shock absorbers	~		
Engine/gearbox oil leak						Air Conditioning / Heater			1
Interior Comments						Operation	~		
stains driver seat rin						Electrical / Accessories			1
Seats						Head lights	~		
Carpets	Average					Tail lights	~		<u> </u>
	Average					Indicators	~		<b> </b>
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		<b> </b>
						Window winder FL		~	<u> </u>
Concret	ommonts					Window winder FR	~		ļ
General	<u>Comments</u>					Window winder RL	~		ļ
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	1	-	
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
с		<u> </u>				Remote locking		~	
-	ming Mechanism:	Cambel				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: John Lindsay						Date: 07 Aug 2019			
Inspected by: John Lindsay Date: 07 Aug 2019									
I have read and understood this condition guide. Name:									