

Report ID: 19,630,225 Version: 2 10 Sep 2019 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:	JHY306	Reg Expiry:	13 Sep 2019	Engine			
WoF Expiry:	06 Sep 2020	Odometer:	92,303 Kms	Good No:	19630225	Oil level	~		
VIN:	MMU148EK0FH62535	Next Service:	103000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SP	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			ZIN	HIL S	Operation	~		
R = rust PT = paint defe	ect NIP			$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent	HIC				JUL	CV joints			~
* = decals	sc 916		<u> </u>	The	EITR	Wheel bearings	~		-
SC = stone chips						Brakes			
W = significant scuffs S S S D S D S D S						Performance 🖌			
		Note: con	ne defects & blemishes			Hand Brake	<i>v</i> <i>v</i>		<u> </u>
Body Insp	pection Comments	Note: son	ne derects & Diemisnes	s may not be disp	nayed in the didgraffi			of +	
						Tyres (lowest observed tread depth of tyres)			
						Left front		5	mm
						Right front		5	mm
						Left rear	4		mm
Conditions During Body Inspection: Wet							Right rear 4.5 mr		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Rear wheel	drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
		Operation 🖌							
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		1
Dashboa	ird					Window winder FL	~		†
	1					Window winder FR	~		<u> </u>
General Comments						Window winder RL	~		<u> </u>
						Window winder RR	~		+
						Rear view mirrors	~		
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	-		~
						Number of keys	2		-
Pond Conditions During Tast Driver Mark						Central locking			
Road Conditions During Test Drive: Wet							v		
Enaine Tir	ming Mechanism:	Timing	Chain			Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
		cincina p		11113.		Reversing camera			~
Inspected	d by: Bobby Zhong					Date: 10 Sep 20	19		

I have read and understood this condition guide.

Name:

Signature: