

Basic Vehicle Condition Guide

Report ID: 19,630,343


Version: 2

Created: 05 Dec 2019

Make: Model: **Body Style:** Foton Tunland Utility Year: 2016 Registration: JQF284 Reg Expiry: 24 Feb 2020 **Odometer:** WoF Expiry: **Good No:** 17 Dec 2020 33,201 Kms 19630343 VIN: LVAV2MBB1FJ058649 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Rear bumper misaligned FL window tint pealed off

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leak around engine and transmission area

Oil leak mark around turbo hose

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	steering wheel worn	

General Comments

Engine noisy

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Xinghui Lin Inspected by:

Create	d: 05	Dec 2	019
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise		~	
Cooling System			
Coolant condition	~		
Performance	<i>v</i>		
Radiator / Hoses (visual)	~		
Transmission	1		
Operation	~		
Noise	~		
Clutch	\(\times \)		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	L es)
Left front	· ·	.5	mm
Right front	6.5		mm
Left rear	6.5		mm
Right rear			mm
Spare		Yes	
Suspension			
Suspension performance	V		
Steering performance	\(\triangle \)		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Tripers (front a real)	ļ •		
Window winder FI	./		
Window winder FL Window winder FR	V		
Window winder FR	~		
Window winder FR Window winder RL	v v		
Window winder FR Window winder RL Window winder RR	\(\times \)		
Window winder FR Window winder RL Window winder RR Rear view mirrors	V V V		
Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	V V V		
Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	V V V V		
Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	\(\times \) \(\t		
Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	V V V V		
Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking Remote locking	\(\times \) \(\t		
Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	\(\times \) \(\t		<i>V</i>

05 Dec 2019

Date:

I have read and understood this condition guide.	Name:	Signature: