

Report ID: 19,630,468 Version: 2 12 Aug 2019 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	LJG452	Reg Expiry:	10 Feb 2020	Engine	1	<u> </u>	I
WoF Expiry:	02 Aug 2020	Odometer:	172,764 Kms	Good No:	19630468	Oil level	~		
VIN:	7AT0C13JX18304942	Next Service:	Freshly serviced	Service Histor	Y: Yes	Smoke & fumes	~		
			·			Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	SC	-0	sc sc	-01-	sc	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sc			215	HIV	Operation	~		
PT = paint defe	ect NP	r I		$\left[\left(\right) \right]$		Noise	V		
C = crack						Clutch	~		
P = pin dent	HIG				74 <u>11</u>	CV joints	V		
* = decals	sc 6/6			The second		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	scuffs SC		SC SC		SC	Performance	~		
Body Incr	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front	3	.0	mm
						Right front	3	.0	mm
						Left rear	1	3	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	V		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
·						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
	-					Remote locking		~	
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Chris Vanner Date: 09 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: