

Report ID: 19,631,012 Version: 2 30 Oct 2019 Created:

Make:	Renault	Model:	Megane	Body Style:	Hatchback] [Pass	Fail	N/A
Year:	2016	Registration:	KGN699	Reg Expiry:	20 Dec 2019	Engine			
WoF Expiry:		Odometer:	65,822 Kms	Good No:	19631012	Oil level	~		
VIN:	VF1BZ360354996478	Next Service:		Service History	V: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		c			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0	S	<u> –</u> –		Radiator / Hoses (visual)	~		
S = scratch	RE	A U			The second	Transmission	-		<u> </u>
D = dent	sc 6/6					Operation	~		
R = rust PT = paint defe					THA	Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent	H				<i>л</i> ш	CV joints	~		
* = decals	sc 916					Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	$\neg \varnothing$	M			Performance	~		
Podulac		Note: som	ne defects & blemis	shes may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed trea	d depth	of tyre	1 2s)
Stone chips on windscreen						Left front 3 mm			
						Right front			mm
						Left rear			mm
Conditions During Body Inspection: Wet						Right rear	4 mm		mm
Conditions During Body Inspection: Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		<u> </u>
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments					Electrical / Accessories			<u> </u>	
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights		~	<u> </u>
	, Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		<u> </u>
General Comments					Window winder RL	~			
Service due	light on					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		1
Road Conditions During Test Drive: Wet Central locking									
						Remote locking	~		
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspecter	d by: Mathew Varghe	ese				Date: 30 Oct 20	19		

I have read and understood this condition guide.

Name:

Signature: