

Report ID: 19,631,374 Version: 3 11 Sep 2019 Created:

Make:	Holden	Model:	Malibu	Body Style:	Sedan		Pass	Fail	N/A
Year:	2013	Registration:	GYQ558	Reg Expiry:	08 Jul 2020	Engine			L
WoF Expiry:	25 Sep 2020	Odometer:	136,917 Kms	Good No:	19631374	Oil level	~		
VIN:	KL3GA69U9DB043184	Next Service:	140000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	unting is goods	for and miles as	Danta hava nat	hoon diamonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0		-01-	Р	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			TIS	SDPTC	Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent	-110				세비	CV joints	~		
* = decals	ssc 919			- NL	ETP s	Wheel bearings	V		
SC = stone chips						Brakes			
W = significant	t scuffs	$- \varnothing$	S S			Performance	~		
Dealerteen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Insp	pection Comments				, ,	Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	3.		mm
						Right front	7		mm
						Left rear	4.		mm
Conditions During Body Inspection: Wet						Right rear	4.5		mm
Conditions During Body inspection. Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Augrage					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	1					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		L
Road Con	ditions During Test	: Drive:	Wet]	Central locking	~		
						Remote locking	~		
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Jason Law Date: 11 Sep 2019									

I have read and understood this condition guide.

Name:

Signature: