

Report ID: 19,631,388 Version: 2 09 Aug 2019 Created:

Make:	BMW	Model:	318	Body Style:	Wagon		Pass	Fail	N/A
Year:	2004	Registration:	GBU536	Reg Expiry:	28 Sep 2019	Engine			-
WoF Expiry:		Odometer:	173,502 Kms	Good No:	19631388	Oil level	~		
VIN:	WBAAX52030JY65840	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	SC S	-0	S S			Radiator / Hoses (visual)	<i>v</i> <i>v</i>		
S = scratch D = dent S SC						Transmission			
R = rust				10		Operation	~		
PT = paint defe	ect			+	P	Noise	~		
C = crack P = pin dent	Ho					Clutch			~
* = decals	s sc pp				ENR S*	CV joints			~
SC = stone chips						Wheel bearings			
W = significant scuffs S P S PT S PT						Brakes		1	
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Left front indicator lens is broken & bottom part of the lens is missing.					Tyres (lowest observed tread depth of tyres)				
						Left front		.8	mm
						Right front	5	.0	mm
						Left rear	5.0		mm
Conditions During Body Inspection: Dry						Right rear	3.6 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil lea	ak from right side of eng	gine.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		1	
						Operation	<ul> <li>✓</li> </ul>		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators		~	
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	iu					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Plastic trim panel missing on right front door interior panel & left rear door interior trim panel has broken off, is sitting in the boot. Both key remotes are not working to lock & unlock vehicle.						Window winder RR	~		
	,		5			Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive:     Dry     Central locking							~		
Remote locking								~	
Engine Timing Mechanism:Timing ChainSat. Nav. (basic test only)Evidence of Cam Belt Replacement:Not ApplicableKms:Reversing camera									~
									~
Inspected by: Jason Young Date: 09 Aug 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....