

Basic Vehicle Condition Guide

Report ID: 19,631,480


Version:

Created: 09 Aug 2019

Make: Model: Ford Courier **Body Style:** Utility Year: 2006 Registration: **DKL947** Reg Expiry: 29 Jun 2020 WoF Expiry: **Odometer:** 11 Apr 2020 157,378 Kms **Good No:** 19631480 VIN: MNABSFE406W50630 Next Service: 166995 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RL taillight lense crack Stone chips on the windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leak around front differential and FR inner drive shaft seal Underbody surface rust

| Interior | Comments |
|----------|----------|
| | |

| | _ |
|-----------|---------------------|
| Seats | FR and FL seat worn |
| Carpets | Average |
| Panels | Average |
| Dashboard | Average |

General Comments

Engine vibration

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt No

Evidence of Cam Belt Replacement:

Kms:

| | Pass | Fail | N/A |
|------------------------------|---|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | • | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | • | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | ~ | | |
| CV joints | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Wheel bearings | ~ | | |
| Brakes | | • | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | 10 |).8 | mm |
| Right front | 10.8 | | mm |
| Left rear | 7 mm | | |
| Right rear | 7 mm | | |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | VVVV | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | V | | |
| Window winder RL | <i>'</i> | | |
| Window winder RR | V | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | ı | |
| Central locking | ~ | | |
| Remote locking | | | ~ |
| Sat. Nav. (basic test only) | | 1 | |

I have read and understood this condition guide.

Sudhin Ramachandran

Name:

Signature:

09 Aug 2019

1

Reversing camera