

Report ID: 19,632,265 Version: 1 09 Aug 2019 Created:

Signature: .....

Make:	Toyota	Model:	Caldina	Body Style:	SUV		Pass	Fail	N/A
Year:	2006	Registration:	HPD295	Reg Expiry:	31 Aug 2019	Engine			<u> </u>
WoF Expiry:	29 Sep 2019	Odometer:	179,512 Kms	Good No:	19632265	Oil level	~		1
VIN:	7AT0H624X14016412	Next Service:	182987	Service Histor		Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		6	Dente have not	harry discover deal and	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	SDR	-0	SDW SP		S D R	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	DPTCSC			10	SDPTCW	Operation	~		
R = rust				$\prod$	JHIH	Noise	~		
PT = paint def C = crack				+	R SC	Clutch	•		~
P = pin dent						CV joints	~		-
* = decals	R PT SC PIE				ELA SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SD W SD W SD R PT W W SD PT W						Performance	~		1
		Note: som				Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	ofture	
Right sill dent						Tyres (lowest observed tread depth of tyres)   Left front 6 mm			
							6		mm
						Right front	6		mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
Under Carriage & Under Bonnet Inspection Comments						· ·	Spare Yes		
Key surround broken						Suspension			1
· ·	erbody oxidisation					Suspension performance	~		
						Steering performance	~		-
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats						Head lights	~		
Carpets	driver mat	and carpet hole				Tail lights	~		
	stains					Indicators	~		──
Panels	Starris					Dashboard warning lights	~		
Dashboa	rd centre cor	nsole lids broken				Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		
General	<u>Comments</u>					Window winder FR	~		
						Window winder RL	~		<b> </b>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2		<del></del>
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Ti	ming Machanism	Cambal	F			Remote locking	~		<u> </u>
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: N	lo	Kms:		Reversing camera	~		
Inspecte	d by: Kyle Mills-Browr	า				Date: 09 Aug 20	19		
						246. 07.4920	-		

I have read and understood this condition guide.

Name: .....