

Report ID: 19,632,491 Version: 5 09 Sep 2019 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2007	Registration:	HWD26	Reg Expiry:	18 Jan 2020	Engine			L	
WoF Expiry:	12 Mar 2020	Odometer:	93,925 Kms	Good No:	19632491	Oil level	~			
VIN:	7AT0GK0CX15410491	Next Service:		Service Histor	y: No	Smoke & fumes	· ·			
						Performance	· ·			
	port is not a warranty		с I II			Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
	ical inspection prior to					Coolant condition	~			
		_				Performance	~			
Key:	SP S	-0	ls			Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent				100	BID	Operation				
R = rust				1 O		Noise	v			
PT = paint def	ect						~			
C = crack P = pin dent	H		لـــال			Clutch			~	
* = decals	PSC DC				Ella	CV joints	~			
SC = stone chi	ps U			10		Wheel bearings	~			
W = significant scuffs						Brakes				
	S			W		Performance	~			
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
						Left front	5.	0	mm	
						Right front	5.	0	mm	
						Left rear	7.	0	mm	
Conditions During Body Inspection: Wet						Right rear	7.0 mm		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
Shock absorbers						Shock absorbers	~			
	Air Conditioning / Heater									
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
						Tail lights	~			
Carpets	Average					Indicators	~			
Deve alla	Average					Dashboard warning lights				
Panels						Wipers (front & rear)	v			
Dashboa	rd Good]		~			
						Window winder FL	~			
General	Comments					Window winder FR	~			
2wd						Window winder RL	~			
2.00						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry Central legendration							~			
	-		•			Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: Bobby Zhong Date: 30 Aug 2019										

I have read and understood this condition guide.

Name:

Signature: