

Report ID: 19,632,525 Version: 3 30 Oct 2019 Created:

Make:	Subaru	Model:	Outback	Body Style:	SUV		Pass	Fail	N/A
Year:	2014	Registration:	HNN254	Reg Expiry:	01 Mar 2020	Engine			
WoF Expiry:		Odometer:	135,306 Kms	Good No:	19632525	Oil level	~		
VIN:	JF2BRMKC5EG064506	Next Service:	145000	Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0		- M-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC D S S						Operation	~		
PT = paint defe		F		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HID				74116	CV joints	~		
* = decals	sc 916					Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments LH wing mirror damaged						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	4 m		mm
						Right front	4	ļ.	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Wet						Right rear	3.4 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
4wd						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
Air Conditioning / I							11		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera							~		
Inspected by: Xinghui Lin Date: 30 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: