

Report ID: 19,632,922 Version: 1 12 Aug 2019 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A	
Year:	2015	Registration:	JCK936	Reg Expiry:	12 May 2019	Engine				
WoF Expiry:	10 Apr 2019	Odometer:	122,230 Kms	Good No:	19632922	Oil level	~			
VIN:	MNAUM2F50FW4091	Next Service:	135333	Service History	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional c	harge.	Coolant condition	~			
						Performance	~			
Key:		-0	S	-161-	s	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust	s sc			715	HIL S	Operation	~			
PT = paint defe				$\left[ \right] \left[ \right]$		Noise	~			
C = crack					SC	Clutch	~			
P = pin dent	HID				74 <u>11</u> 4	CV joints			~	
* = decals	ssc 916			-July	ALC'S	Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
W = significant	scutts S		S		S	Performance	~			
Body Incr	oction Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body inspection comments						Tyres (lowest observed tread	l depth	of tyre	s)	
Aftermarket parts fitted on top of the roof Power converter fitted in canopy						Left front				
Front bumper misaligned						Right front			mm	
						Left rear	6		mm	
Conditions During Body Inspection: Wet						Right rear	6 mm		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Rear wheel	drive					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
	Average					Tail lights	~			
Carpets	, the suge					Indicators	~			
Panels	Average					Dashboard warning lights	~			
	. Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL			~	
						Window winder RR			~	
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1		·	
Road Conditions During Test Drive: Wet Central locking										
						Remote locking	~			
-	ning Mechanism:	Timing (				Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Increate	Inspected by: Xinghui Lin Date: 12 Aug 2019									
Inspected by: Anighur Lin Date: 12 AUG 2019										

I have read and understood this condition guide.

Name: .....

Signature: .....