

Report ID: 19,633,386 Version: 2 13 Aug 2019 Created:

Make:	Audi	Model:	A3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	Registration:		Reg Expiry:	30 Sep 2019	Engine			
WoF Expiry:	05 Apr 2020	Odometer:	128,134 Kms	Good No:	19633386	Oil level	~		
VIN:	WAUZZZ8P0AA00597			Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- Alle			The	EL SC	Operation	~		
R = rust				1 M	JHIH	Noise	~		
PT = paint defe C = crack				+		Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	sc pp			AL-		Wheel bearings	-		
SC = stone chi	ps U	LA		A	& <u> </u>	Brakes	~		
W = significant scuffs						Performance			<u> </u>
		Note: com	Ledefects & blemishes		laved in the diagram	Hand Brake	マ マ		
Body Insp	pection Comments	Note. son	le délects & biennisnes	illay not be disp	layed in the diagram		Ť	- f t 1 1 1 - 1	
					Tyres (lowest observed tread depth of tyres)				
						Left front	6.	-	mm
						Right front	6.	-	mm
						Left rear	6.		mm
Conditions During Body Inspection: Wet						Right rear	6.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & onder bor	<u>ince inspectie</u>	<u>in comments</u>			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	0000					Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		<u> </u>
	Good					Indicators	~		<u> </u>
Panels	Guu					Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Concert						Window winder FR	~		<u> </u>
	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	Drive:	Wet			Central locking	~		
		<u> </u>				Remote locking	~		
-	ming Mechanism:	Cambel				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
	d by: Chris Vanner					Data: 12 Aug 20	10		
Inspected by: Chris Vanner Date: 12 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: