

Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,634,474
Version:	2
Created:	28 Aug 2019

Make:	Honda	Body Style:	Hatchback
Model:	FIT	VIN:	7AT08G2YX19035832
Year:	2009	Odometer:	77,535 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	30 Fuel Flap Release		Cooling System			Exterior			
1	Battery	31	Reversing Camera		55	Coolant Condition		78	Under Carriage	Good	
2	Headlights	32	USB Port		56	Performance		79	Sun Roof Operation	•	
3	Tail Lights	33	Window Lock Swit	tch	57	Radiator/Hoses (visual)		80	Front Windscreen (no chips)	Good	
4	High Stop Light	Tra	nsmission and D	prive	Suspension			81	Back Windscreen (no chips)	Good	
5	Front Right Indicators	34	Operation		58	Suspension Performance		82	Side Windows (no chips)	Good	
6	Front Left Indicators	35	Noise		59	Steering Performance		83	Front Wiper Blades	Good	
7	Rear Right Indicators	36	Clutch	·	60	Shock Absorbers		84	Rear Wiper Blade	Good	
8	Rear Left Indicators	37	CV Joints		Wh	eels and Tyres		85	R/H Mirror	Good	
9	Reversing Lights	38	Wheel Bearing		61	Left Front	4	mm	86	L/H Mirror	Good
10	Rear Reflectors	39	Wheel Balance		62	Right Front	4	mm	87	L/F Guard	Good
11	Hazard Lights	40	Gearbox (Manual)		63	Left Rear	4	mm	88	R/F Guard	Good
12	Courtesy Lights	41	Engine Timing	Timing Chain	64	Right Rear	4	mm	89	L/H Doors	Good
13	Dashboard Lights	42	Evidence of Cam Belt Replacement	Not Applicable	65	Spare	N/A		90	R/H Doors	Good
14	Dashboard Dimmer Switch	43	Replaced at (odometer reading)		66	Tools			91	L/H Sill	Good
15	Number Plate Light	Bra	akes		Interior			92	R/H Sill	Good	
16	Dashboard Warning Lights	44	Front Brakes		67	AC Operation			93	Boot/Tail Gate	Good
17	Speedo	45	Rear Brakes		68	Heater Fan		94	Front Bumper	Good	
18	Odometer	46	Handbrake		69	Seatbelts		95	Rear Bumper	Good	
19	Rev Counter	Key	ys and Locking		70	Horn		96	Roof	Good	
20	Fuel Gauge	47	Central Locking		71	Seat Heaters		97	Bonnet	Good	
21	Wipers Front/Rear	48	Remote Locking		72	Sun Visors		98	Fuel Cap		
22	Window Opener FL	49	Number of Keys 2		73	Sun Visors Lights/Mirrors		99	Mud Flaps		
23	Window Opener FR	Eng	gine		74	Seats	Good		100	WOF	
24	Window Opener RL	50	Oil Level		75	Carpets	Good				
25	Window Opener RR	51	Smokes and Fume	es 🚺	76	Panels	Good				
26	Rear View Mirrors	52	Performance		77	Dashboard	Good				
27	Radio (Basic Test Only)	53	Noise							ers Certification K	ey:
28	CD (Basic Test Only)	54	Starter Motor						$\checkmark = P$ ×= F		
29	Boot Open Switch									lot applicable for thi	s vehicle

Inspected by:	Eddie Marsters	Date:	28 Aug 2019					
I have read and understood this condition guide:								
Name:		Signature:						