



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,634,555
Version:	1
Created:	23 Aug 2019

Make:	Toyota	Body Style:	Hatchback
Model:	Passo	VIN:	7AT0H650X19006324
Year:	2010	Odometer:	69,442 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good					
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•							
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good								
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good						
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th>	59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good						
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good								
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	4	mm	84	Rear Wiper Blade	Good					
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>4</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>4</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	62	Right Front	4	mm	63	Left Rear	4	mm	85	R/H Mirror	Good			
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>64</td> <td>Right Rear</td> <td>4</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>Yes</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	64	Right Rear	4	mm	65	Spare	Yes	86	L/H Mirror	Good				
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>66</td> <td>Tools</td> <th>✓</th> <td>87</td> <td>L/F Guard</td> <td>Good</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	66	Tools	✓	87	L/F Guard	Good	88	R/F Guard	Good					
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	Interior		67	AC Operation	✓	89	L/H Doors	Good	90	R/H Doors	Good			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	68	Heater Fan	✓	69	Seatbelts	✓	91	L/H Sill	Good	92	R/H Sill	Good		
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓	71	Seat Heaters	•	93	Boot/Tail Gate	Good	94	Front Bumper	Good		
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	95	Rear Bumper	Good	96	Roof	Good		
14	Dashboard Dimmer Switch	•	Brakes		44	Front Brakes	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>76</td> <td>Panels</td> <td>Good</td> <td>77</td> <td>Dashboard</td> <td>Good</td>	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good
15	Number Plate Light	✓	45	Rear Brakes	✓ <th colspan="2">Keys and Locking</th> <td>78</td> <td>Fuel Cap</td> <th>✓</th> <td>79</td> <td>Mud Flaps</td> <th>✓</th> <td>80</td> <td>WOF</td> <th>✓</th>	Keys and Locking		78	Fuel Cap	✓	79	Mud Flaps	✓	80	WOF	✓			
16	Dashboard Warning Lights	✓	46	Handbrake	✓ <td>47</td> <td>Central Locking</td> <th>✓<td>48</td><td>Remote Locking</td><th>✓<td>49</td><td>Number of Keys</td><td>1</td><th colspan="2">Engine</th></th></th>	47	Central Locking	✓ <td>48</td> <td>Remote Locking</td> <th>✓<td>49</td><td>Number of Keys</td><td>1</td><th colspan="2">Engine</th></th>	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <th colspan="2">Engine</th>	49	Number of Keys	1	Engine				
17	Speedo	✓	Keys and Locking		50	Oil Level	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>52</td><td>Performance</td><th>✓<td>53</td><td>Noise</td><th>✓</th></th></th>	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>53</td><td>Noise</td><th>✓</th></th>	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓</th>	53	Noise	✓			
18	Odometer	✓	50	Oil Level	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>52</td><td>Performance</td><th>✓<td>53</td><td>Noise</td><th>✓<td>54</td><td>Starter Motor</td><th>✓</th></th></th></th>	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>53</td><td>Noise</td><th>✓<td>54</td><td>Starter Motor</td><th>✓</th></th></th>	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>54</td><td>Starter Motor</td><th>✓</th></th>	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓</th>	54	Starter Motor	✓		
19	Rev Counter	•	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>53</td><td>Noise</td><th>✓<td>54</td><td>Starter Motor</td><th>✓</th></th></th>	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>54</td><td>Starter Motor</td><th>✓</th></th>	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓</th>	54	Starter Motor	✓					
20	Fuel Gauge	✓	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>54</td><td>Starter Motor</td><th>✓</th></th>	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓</th>	54	Starter Motor	✓								
21	Wipers Front/Rear	✓	53	Noise	✓														
22	Window Opener FL	✓	54	Starter Motor	✓														
23	Window Opener FR	✓																	
24	Window Opener RL	✓																	
25	Window Opener RR	✓																	
26	Rear View Mirrors	✓																	
27	Radio (Basic Test Only)	✓																	
28	CD (Basic Test Only)	✓																	
29	Boot Open Switch	✓																	

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	John Lindsay	Date:	23 Aug 2019
---------------	--------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--