

# **Basic Vehicle Condition Guide**

Report ID: 19,634,806

Pass

Version: 2

Engine

Created: 14 Aug 2019


Fail

N/A

Make: Model: Honda Stream **Body Style:** SUV Year: 2005 Registration: HLY938 **Reg Expiry:** 01 Sep 2019 WoF Expiry: **Odometer:** 23 Feb 2020 214,148 Kms **Good No:** 19634806 VIN: 7AT08GADX14001778 Next Service: **Service History:** 

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



### **Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

LF park light not going. Headlamps need buffing. Clearcoat is coming off vehicle. Tow eye cover in rear bumper missing. Tailgate and rear bumper damaged.

AC not cold. LF window has issues. Wear on steering wheel. Tweeter speaker on LF door damaged. Wear on center LH seat.

Conditions During Body Inspection: Dry

## **Under Carriage & Under Bonnet Inspection Comments**

LR swaybar link worn. Engine has oil seepage. Surface rust under floor mostly at rear. Both front guard liners are damaged.

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

# **General Comments**

Front bumper lamps missing. Front bumper damaged. Both weatherstrips on RH doors are worn. Remote locking not working. Gear lever knob is worn.

Drives ok.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Roger King

Evidence of Cam Belt Replacement: No Kms:

Oil level	>				
Smoke & fumes	>				
Performance	\ \ \				
Noise	>				
Cooling System					
Coolant condition	~				
Performance	~				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	~				
Clutch			~		
CV joints	/				
Wheel bearings	~				
Brakes			•		
Performance	~				
Hand Brake	>				
Tyres (lowest observed tread depth of tyres)					
Left front	į	5	mm		
Right front	į	5	mm		
Left rear	3		mm		
Right rear	3		mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	~				
Shock absorbers	<b>'</b>				
Air Conditioning / Heater					
Operation 🗸					
Electrical / Accessories					
Head lights	~				
Tail lights	>				
Indicators	>				
Dashboard warning lights	>				
Wipers (front & rear)	/				
Window winder FL	/				
Window winder FR	V V V V V				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	<b>'</b>				
CD (basic test only)	~				
,,					
Number of keys	1				
Number of keys  Central locking	-				
Number of keys	-	~			
Number of keys  Central locking	-	V	V		

I have read and understood this condition guide.

Name: .....

Signature: .....

14 Aug 2019

Date: