

# **Basic Vehicle Condition Guide**


Report ID: 19,775,999

Version: 3

Make: Model: Holden Colorado **Body Style:** Utility Year: 2011 Registration: **GAG886** Reg Expiry: 09 Nov 2019 WoF Expiry: **Odometer:** 30 Oct 2020 182,697 Kms **Good No:** 19775999 VIN: MMMTFS85JBH54373 Next Service: 187,500 Service History:

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



### **Body Inspection Comments**

Front bumper misaligned, RH side trim missing.

RH fog lamp dummy missing

Front grille cracked.

Antenna broken.

**Conditions During Body Inspection:** Dry

## **Under Carriage & Under Bonnet Inspection Comments**

Gearbox oil leak

Front differential minor seepage

Underbody surface rust

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

## **General Comments**

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Inspected by: Mathew Varghese

Create	Created: 21 Oct 2019		
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	~		
Noise	~		
Clutch	\( \times \)		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed trea	d depth	of tyre	es)
Left front	(	5	mm
Right front	(	5	mm
Left rear	(	5	mm
Right rear	(	5	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights		~	
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR	1		~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~

Reversing camera

21 Oct 2019

1