

Report ID: 19,776,663 Version: 2 28 Sep 2019 Created:

Make:	Hyundai	Model:	Sonata	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2015	Registration:	JHL945	Reg Expiry:	10 Sep 2019	Engine				
	25 Sep 2020	Odometer:	65,648 Kms	Good No:	19776663	Oil level	~			
VIN:	KMHE241FMFA11162			Service Histor		Smoke & fumes	~			
					,	Performance	~			
	port is not a warranty					Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
		_				Performance	~			
Key:		-0	ls		s	Radiator / Hoses (visual)	~			
S = scratch	Se	20		105	*	Transmission	V			
D = dent	IS ALE			100	EID S				1	
R = rust				10	JHIN	Operation Noise	~ ~			
PT = paint def C = crack	ect M			+		Clutch	V			
P = pin dent	Ho								~	
* = decals	sc pp			SI_	Ell'As	CV joints Wheel bearings	~			
SC = stone chi	ps V	VA		10			~		1	
W = significant scuffs SC S S S S S						Brakes			1	
		Nataraa				Performance	~			
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~	<u> </u>	Ļ	
						Tyres (lowest observed tread depth of tyres)				
FL tyre side wall cut Pin dent on FR door frame						Left front	7.		mm	
						Right front	7.	-	mm	
						Left rear	6		mm	
Conditions During Body Inspection: Dry						Right rear	5.8 mm			
Under Carriage & Under Pennet Inspection Comments					Spare					
Under Carriage & Under Bonnet Inspection Comments Front wheel drive						Suspension				
Front whee	l drive					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation				
Interior Comments Good						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	~			
						Window winder FL	~			
	_					Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry Central locking							~			
						Remote locking	~			
-	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Bobby Zhong Date: 28 Sep 2019										

I have read and understood this condition guide.

Name: