

Report ID: 19,776,732 Version: б 30 Sep 2019 Created:

Make:	Mazda	Model:	Mazda3	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	Registration:	MHK314	Reg Expiry:	05 Jul 2020	Engine			
WoF Expiry:	25 Sep 2020	Odometer:	124,927 Kms	Good No:	19776732	Oil level	~		
VIN:	JM0BK103100206436	Next Service:	128,500	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and ti	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
			S S		S	Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	1		
D = dent R = rust						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W PT W S						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Fine chips on front windscreen									mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation 🖌			
Interior Comments						Electrical / Accessories	-		
Seats Good						Head lights	~		
	A. 1978 810					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	1	L
Road Conditions During Tost Driver						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
L	•		••						_
Inspected by: Jason Law Date: 26 Sep 2019									

I have read and understood this condition guide.

Name:

Signature: