

Basic Vehicle Condition Guide

Report ID: 19,776,750

Pass

1

~

/

V

1

3.5

3.5

3.5

3.5

1

/

/

/

1

1

2

Yes

Tyres (lowest observed tread depth of tyres)

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Suspension performance

Steering performance

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of kevs

Shock absorbers Air Conditioning / Heater

Operation

Head lights Tail lights Indicators

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 01 Oct 2019

Fail

N/A

1

mm

mm


mm

 mm

Make: Model: Holden Viva **Body Style:** Sedan Year: 2006 Registration: **DED883 Reg Expiry:** 01 Jul 2020 WoF Expiry: **Odometer:** 26 Sep 2020 157,978 Kms **Good No:** 19776750 VIN: KL3NA19BJ6K292101 **Next Service:** 165700 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips on front windscreen Wiper scratch mark on windscreen Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

<u>Interior Comments</u>		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

Cluster lens cracked

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Bobby Zhong

I have read and understood this condition guide.

	Central locking	V	
	Remote locking	~	
	Sat. Nav. (basic test only)		V
Kms:	Reversing camera		~
	Date: 01 Oct 20	19	
Name:	Signature:		