

Basic Vehicle Condition Guide

Report ID: 19,778,823


Version:

Created: 19 Aug 2019

Make: Model: Holden Colorado **Body Style:** Utility Year: 2016 Registration: JQA415 Reg Expiry: 10 Aug 2019 **Odometer:** WoF Expiry: **Good No:** 20 May 2020 163,051 Kms 19778823 VIN: MMU148MK0GH6309 Next Service: Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Damage on Tonneau cover. Stonechips on windscreen.

Chrome on gear knob sharp on front edge. Heater Fan strength on upper body not strong. Wear on RF seat and seatbelt.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Both sides, rear shock bushes, upper and lower are worn.

| Interior Comments | | |
|-------------------|---------|--|
| Seats | Average | |
| Carpets | Average | |
| Panels | Average | |
| Dashboard | Average | |

General Comments

Inspected by:

Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Roger King

Evidence of Cam Belt Replacement: No

Kms: 19 Aug 2019 Date:

| | Pass | Fail | N/A |
|------------------------------|---|---------|----------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | \(\triangle \) | | |
| Noise | ~ | | |
| Cooling System | | | • |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | V V | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ' | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | l depth | of tyre | ! es) |
| Left front | | | mm |
| Right front | 2 | | mm |
| Left rear | 2 | | mm |
| Right rear | | | mm |
| Spare | | Yes | |
| Suspension | | 103 | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | | ~ | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | <i>'</i> | | |
| Dashboard warning lights | \(\triangle \) | | |
| Wipers (front & rear) | | | |
| Window winder FL | <i>'</i> | | |
| Window winder FR | ~ | | |
| Window winder RL | VVV | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | • | | |
| CD (basic test only) | | | V |
| Number of keys | 2 | | _ |
| Central locking | | | |
| | 1 | | |
| Remote locking | | | |
| Sat. Nav. (basic test only) | | | - |
| Reversing camera | | | |

I have read and understood this condition guide.

| Name [.] | |
|-------------------|--|

| Signature | |
|-----------|--|
| | |