

Basic Vehicle Condition Guide

Report ID: 19,779,152


Version: 2

Created: 20 Aug 2019

Make: Model: Mazda Bt-50 **Body Style:** Utility Year: 2014 Registration: HMG324 Reg Expiry: 16 Sep 2019 WoF Expiry: **Odometer:** 25 Jun 2020 141,785 Kms **Good No:** 19779152 VIN: MM0UP0YF10021250! Next Service: 145,729kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front bumper misaligned + holes/Metal plate fitted on tailgate/Badges missing/RL mudflap damagemissing/Gear knob damage/Reverse camera loose

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Rear wheel drive

Interior Comment	<u>s</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	>			
Performance	\(\times \)			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	'			
Radiator / Hoses (visual)	~			
Transmission		•		
Operation	~			
Noise	<i>y y</i>			
Clutch	/			
CV joints			~	
Wheel bearings	/			
Brakes				
Performance	~			
Hand Brake	>			
Tyres (lowest observed tread	depth	of tyre	es)	
Left front	5.5		mm	
Right front	5.5		mm	
Left rear	5.5		mm	
Right rear	6		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators				
indicators	'			
Dashboard warning lights	✓ ✓			
	VVV			
Dashboard warning lights				
Dashboard warning lights Wipers (front & rear)				
Dashboard warning lights Wipers (front & rear) Window winder FL	> > > > > > > > > > > > > > > > > > >			
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR				
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL	ン ン ン			
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR	\(\times \)			
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	\(\times \) \(\t			
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	V V V V			
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	V V V V V			
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	VVVVVZ			

I have read and understood this condition guide.

Name:

Signature:

20 Aug 2019

Reversing camera