

## **Basic Vehicle Condition Guide**

Report ID: 19,780,184


Version: 2

Created: 30 Aug 2019

Make: Model: 120 Hyundai **Body Style:** Hatchback Year: 2016 Registration: KAB515 Reg Expiry: 30 Jan 2020 **WoF Expiry: Odometer: Good No:** 13 Aug 2020 31,403 Kms 19780184 VIN: MALBB51CMGM7065; Next Service: 41400 Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

**General Comments** 

2wd

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Inspected by: Jason Law 30 Aug 2019 Date:

Pass Fail	N/A
V	
V	
V V	
V	
V	
V	
al) 🗸	
V	
V	
	~
V	
V	
V	Ι
- L	
tread depth of tyre	L es)
2	mm
6	mm
2	mm
6	mm
Yes	
163	
nce 🗸	
<i>y</i>	
- V	
ter	
14	
v	
ghts 🗸	
ghts V	
<i>v</i>	
<i>'</i>	
<i>V</i>	
<i>'</i>	
V	
<i>'</i>	
2	1
<b>V</b>	
· · ·	
ly)	~
· /	
ly) 🗸	

I have read and understood this condition guide.

Name: .....

Signature: .....