

Report ID: 19,780,420 Version: 1 19 Aug 2019 Created:

Make:	Volkswagen	Model:	Jetta	Body Style:	Sedan		Pass	Fail	N/A
Year:	2007	Registration:		Reg Expiry:	09 Jul 2020	Engine	I	<u> </u>	
WoF Expiry:	17 May 2020	Odometer:	111,395 Kms	Good No:	19780420	Oil level	~		
VIN:	WVWZZZ1KZ7M1010	Next Service:	118000	Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		6	Danta hava nat	harria diamandarahari	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	s w	-0	SD S		S R PT	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	C SC W			The	EID S	Operation	~		
R = rust PT = paint defe				\prod	JHH	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	Ho					CV joints	~		•
* = decals	PT SC PIK			- AL	ELA SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W S D S D W S						Performance	~		
		Natarcom	ne defects & blemishes			Hand Brake	<i>v</i> <i>v</i>		
· · ·	pection Comments		le delects à blemistie	s may not be disp	ayed in the diagram		-	ofture))
Front bumper right side alignment Chip windscreen outside CVA						Tyres (lowest observed tread depth of tyres)			
Front lip alignment						Left front		3	mm
						Right front		1	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	-	meemspeede	<u>Comments</u>			Suspension			
Roof lining	Stallis					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	//veluge					Head lights	~		
Carpets	Average					Tail lights	~		
	A. 1010 0.0					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	ashtray lid	broken				Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 99,452						Reversing camera			~
Inspected by: John Lindsay Date: 19 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: