

Basic Vehicle Condition Guide

Report ID: 19,780,761


Version: 4

Created: 29 Aug 2019

Make: Model: IST Toyota **Body Style:** Hatchback Year: 2006 Registration: HEC815 Reg Expiry: 08 Jul 2020 WoF Expiry: **Odometer:** 06 Sep 2020 100,969 Kms **Good No:** 19780761 VIN: 7AT0H647X13002862 Next Service: 111000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



body inspection comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

OK.

| Interior Comment | <u>s</u> |
|------------------|-----------------------|
| Seats | Average |
| Carpets | Hole on drivers side. |
| Panels | Average |
| Dashboard | Average |

General Comments

Nice little hatch.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Daryll Timms Date: 21 Aug 2019

Name:

| Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes | | | v |
|---|---------------------------------------|---------|----------|
| Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes | | | v |
| Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes | | | v |
| Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes | | | · · · |
| Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes | | | · · |
| Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | · · |
| Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | ~ |
| Transmission Operation Noise Clutch CV joints Wheel bearings Brakes | <i>y y y y y y y y y y</i> | | V |
| Transmission Operation Noise Clutch CV joints Wheel bearings Brakes | <i>y y y y y y y y y y</i> | | · |
| Operation Noise Clutch CV joints Wheel bearings Brakes | | | V |
| Noise (Clutch CV joints (Wheel bearings Brakes | | | · |
| Clutch CV joints Wheel bearings Brakes | \ \ \ \ | | <i>'</i> |
| CV joints (Wheel bearings (Brakes | \ \ \ | | V |
| Wheel bearings | \ \ \ | | |
| Brakes | <i>y</i> | | |
| 2 (| ' | | |
| Performance | / | | |
| 1 chombine | | | |
| Hand Brake | | | |
| Tyres (lowest observed tread d | lepth | of tyre | es) |
| Left front | 5. | .0 | mm |
| Right front | 3. | .0 | mm |
| Left rear | 4. | .0 | mm |
| Right rear | 5. | .0 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | ' | | |
| Shock absorbers | / | | |
| Air Conditioning / Heater | | | |
| Operation | \ | | |
| Electrical / Accessories | | | |
| Head lights | < | | |
| Tail lights | / | | |
| Indicators | / | | |
| Dashboard warning lights | \ | | |
| Wipers (front & rear) | < | | |
| Window winder FL | \ | | |
| Window winder FR | / | | |
| Window winder RL | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | / | | |
| | / | | |
| CD (basic test only) | / | | |
| Number of keys 1 | | | |
| Central locking | ~ | | |
| Remote locking | ' | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |

Signature: