

Report ID: 19,781,120 Version: 1 29 Aug 2019 Created:

| Make: | Mercedes-Benz | Model: | B-Class | Body Style: | Hatchback | | Pass | Fail | N/A | |
|--|--|-----------------------|------------------------|-----------------|----------------------|--|----------------------|--------|-----|--|
| Year: | 2014 | | HKS48 | Reg Expiry: | 29 Apr 2020 | Engine | | | | |
| WoF Expiry: | | Odometer: | 72,219 Kms | Good No: | 19781120 | Oil level | ~ | | | |
| VIN: | WDD2462432J241643 | Next Service: | | Service Histor | y: Yes | Smoke & fumes | ~ | | | |
| | | | | | | Performance | ~ | | | |
| | port is not a warranty | | с I II | | | Noise | ~ | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | | | | |
| | | | | | | Performance | ~ | | | |
| Key: | | -0 | SC SC | | | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | Transmission | | | | |
| D = dent | sc 6/6 | | | 1n- | EIU | Operation | ~ | | | |
| R = rust | | | | 10 | JHIL | Noise | ~ | | | |
| PT = paint defe C = crack | | | | + | | Clutch | • | | ~ | |
| P = pin dent | Ho | | | | | CV joints | ~ | | | |
| * = decals | - MIK | | | AL- | | Wheel bearings | - | | | |
| SC = stone chips | | | | | | Wheel bearings | | | | |
| W = significant scuffs W SC SC W | | | | | | Performance | ~ | | | |
| | | Noto: com | ne defects & blemishes | | laved in the diagram | Hand Brake | <i>v</i> <i>v</i> | | | |
| Body Insp | pection Comments | 10000.3011 | le delects & blemisnes | may not be disp | layed in the diagram | | • | ofture | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | | | | | Left front | 3 | | mm | |
| | | | | | | Right front | 3. | | mm | |
| | | | | | | Left rear | 4.0 | | mm | |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 4. | 4.0 mn | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | | |
| | | <u>ince inspectie</u> | <u>in comments</u> | | | Suspension | | | - | |
| · · | | | | | | Suspension performance | ~ | | | |
| | | | | | | Steering performance | ~ | | | |
| | | | | | | Shock absorbers | ~ | | | |
| | | | | | | Air Conditioning / Heater | 1 | | | |
| Interior Comments | | | | | | Operation 🖌 | | | | |
| Good | | | | | | Electrical / Accessories | | | | |
| Seats | 0000 | | | | | Head lights | ~ | | | |
| Carpets | Good | | | | | Tail lights | ~ | | | |
| | Cood | | | | | Indicators | ~ | | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | | |
| Dashboa | Good Good | | | | | Wipers (front & rear) | ~ | | | |
| | | | | | | Window winder FL | ~ | | | |
| Campada | | | | | | Window winder FR | ~ | | | |
| General | <u>Comments</u> | | | | | Window winder RL | ~ | | | |
| · | | | | | | Window winder RR | ~ | | | |
| | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | Number of keys | 2 | | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | | |
| Engine Timing Mechanismu Timing Chain | | | | | | Remote locking | ~ | | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | ~ | | | |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | | |
| Inspected | Inspected by: Chris Vanner Date: 20 Aug 2019 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: