

Basic Vehicle Condition Guide

Report ID: 19,783,684


Version:

Created: 22 Aug 2019

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2015 Registration: HYQ65 **Reg Expiry:** 12 Nov 2019 WoF Expiry: **Odometer:** 13 Feb 2020 215,326 Kms **Good No:** 19783684 VIN: MR0EZ12GX04158853 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Name:

Paint spilled on rear bumper. Wiring running over roof of canopy. RF wheel center cap missing. Both C pillars have stone chips at bottom. Large dent in LH sill. Stonechips on windscreen. RF door body rubber has wear. Cigarette burn in RF seat. Wear on steering wheel.

Center rear seatbelt has wear.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Average condition.

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

General Comments

RF seat and seatbelt are worn. Mic holder screwed to dash. Cigarette lighter socket damaged.

Drives ok.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Roger King

Evidence of Cam Belt Replacement: No Kms:

22 Aug 2019

Date:

Signature:

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	\(\times \)				
Performance	~				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	\(\triangle \)				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	<i>V V</i>				
Clutch	~				
CV joints			~		
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread depth of tyres)					
Left front	***	3	mm		
Right front	1	3	mm		
Left rear	į	5	mm		
Right rear	I,	5	mm		
Spare		Yes			
Suspension					
Suspension performance	v v				
Steering performance	~				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	\(\times \)				
Wipers (front & rear)	~				
Window winder FL	'				
Window winder FR	~				
Window winder RL	~				
Window winder RR	\(\times \)				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)	~				
Number of keys	1				
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Reversing camera	•				