

Report ID: 19,783,936 Version: 2 27 Aug 2019 Created:

| Make:  | Toyota                       | Model:          | Landcruiser           | Body Style:        | SUV  |                             | Pass        | Fail N/A     |
|--|------------------------------|-----------------|-----------------------|--------------------|--|-----------------------------|-------------|--------------|
| Year:  | 2006                         |                 | JDT472                | Reg Expiry:        | 11 Dec 2019                                  | Engine                      | 1 455       | - un   , / . |
| WoF Expiry:  | 03 Aug 2020                  | Odometer:       | 206,611 Kms           | Good No:           | 19783936                                     | Oil level                   | ~           |              |
| VIN:   | 7AT0H60HX15044782            |                 | ,                     | Service Histor     |  | Smoke & fumes               | ~           |              |
|  | 7 41 01 1001 17 1 30 44 7 82 | Heat Service.   | 215,52081113          |                    | <b>y.</b> NO                                 | Performance                 | ~           |              |
|  | port is not a warranty       |                 |                       |                    |  | Noise                       | ~           |              |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends |                              |                 |                       |                    |  |                             |             |              |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge.  |                              |                 |                       |                    |  |                             |             |              |
|  |                              |                 |                       |                    |  | Performance                 | ~           |              |
| Key:   | SC                           | -0              | SC SC                 |                    | SC   |                             | ~           |              |
| S = scratch  | re                           | - (U)           | AT                    | 10/2               | ~  | Radiator / Hoses (visual)   | ~           |              |
| D = dent   | sc all                       |                 |                       |                    | All IS                                       | Transmission                |             |              |
| R = rust   |                              |                 |                       | 10                 |  | Operation                   | ~           |              |
| PT = paint defe  | ect                          |                 |                       | +                  |  | Noise                       | ~           |              |
| C = crack<br>P = pin dent  | Ho                           |                 |                       |                    |  | Clutch                      |             | ~            |
| *= decals SC Q Q   |                              |                 |                       |                    |  | CV joints                   | ~           |              |
| SC = stone chips   |                              |                 |                       |                    |  | Wheel bearings              | ~           |              |
| W = significant scuffs S SC W  |                              |                 |                       |                    |  | Brakes                      | <u>г.</u> г |              |
|  |                              |                 |                       |                    |  | Performance                 | ~           |              |
| Body Insp  | pection Comments             | Note: som       | ne defects & blemishe | es may not be disp | layed in the diagram                         | Hand Brake                  | ~           |              |
| Fine chips on screen.  |                              |                 |                       |                    | Tyres (lowest observed tread depth of tyres) |                             |             |              |
|  |                              |                 |                       |                    |  | Left front                  | 6.0         | mm           |
|  |                              |                 |                       |                    |  | Right front                 | 6.0         | mm           |
|  |                              |                 |                       |                    |  | Left rear                   | 6.0         | mm           |
| Conditions During Body Inspection: Dry   |                              |                 |                       |                    |  | Right rear                  | 7.0         | mm           |
|  |                              |                 |                       |                    |  | Spare Yes                   |             |              |
| Under Carriage & Under Bonnet Inspection Comments  |                              |                 |                       |                    |  | Suspension                  |             |              |
| Tidy.  |                              |                 |                       |                    |  | Suspension performance      | ~           |              |
|  |                              |                 |                       |                    |  | Steering performance        | ~           |              |
|  |                              |                 |                       |                    |  | Shock absorbers             | ~           |              |
|  |                              |                 |                       |                    |  | Air Conditioning / Heater   |             |              |
|  |                              |                 |                       |                    |  | Operation 🖌                 |             |              |
| Interior Comments  |                              |                 |                       |                    |  | Electrical / Accessories    |             |              |
| Seats  | small rip o                  | n drivers seat. |                       |                    |  | Head lights                 | ~           |              |
| Carpote  | Average                      |                 |                       |                    |  | Tail lights                 | ~           |              |
| Carpets  |                              |                 |                       |                    |  | Indicators                  | ~           |              |
| Panels   | Average                      |                 |                       |                    |  | Dashboard warning lights    | ~           |              |
|  | , Good                       |                 |                       |                    |  | Wipers (front & rear)       | ~           |              |
| Dashboa  | iiu                          |                 |                       |                    |  | Window winder FL            | ~           |              |
|  |                              |                 |                       |                    |  | Window winder FR            | ~           |              |
| General Comments   |                              |                 |                       |                    |  | Window winder RL            | ~           |              |
| Nice tidy 8  | seater 4WD SUV.              |                 |                       |                    |  | Window winder RR            | ~           |              |
|  |                              |                 |                       |                    |  | Rear view mirrors           | ~           |              |
|  |                              |                 |                       |                    |  | Radio (basic test only)     | ~           |              |
|  |                              |                 |                       |                    |  | CD (basic test only)        |             | ~            |
|  |                              |                 |                       |                    |  | Number of keys              | 1           |              |
| Road Conditions During Test Drive: Dry   |                              |                 |                       |                    |  | Central locking             | ~           |              |
|  | -                            |                 | •                     |                    |  | Remote locking              | ~           |              |
| Engine Timing Mechanism: Timing Chain  |                              |                 |                       |                    |  | Sat. Nav. (basic test only) |             | ~            |
| Evidence   | of Cam Belt Replac           | ement: N        | lot Applicable        | Kms:               |  | Reversing camera            |             | ~            |
| Inspected by: Daryll Timms Date: 22 Aug 2019   |                              |                 |                       |                    |  |                             |             |              |

Name: .....