


<b>Make:</b> Nissan	<b>Model:</b> Vanette	<b>Body Style:</b> Van
<b>Year:</b> 2008	<b>Registration:</b> LYF832	<b>Reg Expiry:</b> 18 Jul 2019
<b>WoF Expiry:</b> 04 Feb 2020	<b>Odometer:</b> 157,010 Kms	<b>Good No:</b> 19784382
<b>VIN:</b> 7AT0DH19X18203508	<b>Next Service:</b>	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

LF window not working. All rear windows painted out. LR guard has damage. LH D pillar has cracks in inside by threaded hole. Rust marks on inside of tailgate on seam at top. Rust marks under RF mirror mount. House paint splashes on vehicle. Paint splashes on seats, dash steering wheel, door cards.

Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments**

Rear shackle bushes perished. Front tyres unsafe.

**Interior Comments**

Seats	Poor
Carpets	Poor
Panels	Poor
Dashboard	Average

**General Comments**

Engine is noisy when cold. Stonechips on windscreen. Wire exposed in RF tyre.  
Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt  
Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front	1.4	mm	
Right front	0	mm	
Left rear	2	mm	
Right rear	2	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL		✓	
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Roger King

Date: 09 Sep 2019

I have read and understood this condition guide. Name: ..... Signature: .....