

Report ID: 19,785,190 Version: 2 06 Nov 2019 Created:

Make:	Ford	Model:	Fiesta	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010	Registration:	FQC724	Reg Expiry:	01 Jun 2020	Engine			<u> </u>
WoF Expiry:		Odometer:	137,503 Kms	Good No:	19785190	Oil level	~		
VIN:	WF0JXXGAJJAU79980	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
		_				Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	Se	20			X	Transmission	V		
D = dent				The	BID SC	Operation			T
R = rust				10		Noise	~ ~		
PT = paint defe C = crack	ect III			+		Clutch	V		
P = pin dent	Ho								~
* = decals	MIC					CV joints	~		
SC = stone chi	ps U	VA		10		Wheel bearings	~		
W = significant	t scuffs	-0				Brakes			1
		N				Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	<ul> <li>✓</li> </ul>		Ļ
						Tyres (lowest observed tread depth of tyres)			
						Left front	8.	.0	mm
						Right front	8.	.0	mm
						Left rear	8	3	mm
Conditions During Body Inspection: Dry						Right rear	8 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Under Ca	rrlage & Under Bor	inet inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
la tarian C						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Deal-L	rd Average					Wipers (front & rear)	~		
Dashboa	iu y					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			·			Remote locking	~		
-	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Dion Mair Date: 28 Aug 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....