

I have read and understood this condition guide.

Report ID: 19,785,922 Version: 2 24 Sep 2019 Created:

Signature: .....

Make:	BMW	Model:	1 Series	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	<b>Registration:</b>	KNZ215	<b>Reg Expiry:</b>	04 Nov 2019	Engine			
WoF Expiry:	10 Jul 2020	Odometer:	177,389 Kms	Good No:	19785922	Oil level	~		
VIN:	WBAUF12090PZ30874	Next Service:	182000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S SC S * S*						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints			V
* = decals	- Ole			- Jul		Wheel bearings	~		
SC = stone chips						Brakes	-		
W = significant scuffs						Performance	~		
Dealerteen		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
Ariel missing						Left front 6.7 mm			
						Right front		.7	mm
						Left rear		4.1 mm	
Conditions During Body Inspection: Dry						Right rear		.1	mm
Conditions During Body Inspection: Dry						Spare No			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Seats Good					Head lights	~		
	A					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Audio screen pixelated						Window winder RR	~		
this car has starter motor issue hence needs new starter motor						Rear view mirrors	~		
further investigation or independent check up suggested						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking			
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	+		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Stuart Melbourne Date: 23 Aug 2019									

Name: .....