

Report ID: 19,786,379 Version: 1 25 Aug 2019 Created:

Make:	Hyundai	Model:	130	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	Registration:	FTZ825	Reg Expiry:	30 Jan 2020	Engine			
WoF Expiry:	16 Aug 2020	Odometer:	242,850 Kms	Good No:	19786379	Oil level	~		
VIN:	KMHDB51DMBU31094	Next Service:	250,221	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	W		S S		S	Performance	~		
Key:		-0	S S	-0×		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC S S						Operation	~		
PT = paint defe		r I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					D PT SC	Clutch			~
P = pin dent	HIP				2414	CV joints	~		
* = decals	sc 916					Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Podulac	action Commonts	Note: som	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	l depth	of tyre	es)
Remote not working								mm	
						Right front		5	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Front whee	l drive					Suspension performance	~		
Underbody	surface rust					Steering performance	· ·		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	N. flaame	-4-				Tail lights	~		
Carpets	No floor m	ats				Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	• •		
						Window winder RR	• •		
						Rear view mirrors	• •		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	I	
Road Conditions During Test Drive: Wet						Central locking	· •		
	unions During Test	Dive:	Wet			Remote locking	-	~	
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)		•	~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	- F		- F F						•
Inspected by: Mathew Varghese Date: 25 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: