



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,786,604
Version:	1
Created:	26 Aug 2019

Make:		Body Style:	
Model:		VIN:	7AT0CJ3MX19003860
Year:		Odometer:	53,346 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good		
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good		
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good		
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good
4	High Stop Light	✓	Transmission and Drive		Wheels and Tyres		59	Steering Performance	✓	60	Shock Absorbers	✓	85	R/H Mirror	Good	
5	Front Right Indicators	✓	34	Operation	✓	61	Left Front	5	mm	62	Right Front	5	mm	86	L/H Mirror	Good
6	Front Left Indicators	✓	35	Noise	✓	63	Left Rear	5	mm	64	Right Rear	5	mm	87	L/F Guard	Good
7	Rear Right Indicators	✓	36	Clutch	•	65	Spare	N/A	66	Tools	✓	88	R/F Guard	Good		
8	Rear Left Indicators	✓	37	CV Joints	✓	67	AC Operation	✓	68	Heater Fan	✓	89	L/H Doors	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓	69	Seatbelts	✓	70	Horn	✓	90	R/H Doors	Good		
10	Rear Reflectors	✓	39	Wheel Balance	✓	71	Seat Heaters	•	72	Sun Visors	✓	91	L/H Sill	Good		
11	Hazard Lights	✓	40	Gearbox (Manual)	•	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	92	R/H Sill	Good		
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	75	Carpets	Good	76	Panels	Good	93	Boot/Tail Gate	Good		
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	77	Dashboard	Good	78	Fuel Cap	✓	94	Front Bumper	Good		
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		Interior		79	Fuel Cap	✓	95	Rear Bumper	Good	96	Roof	Good
15	Number Plate Light	✓	Brakes		Interior		80	Fuel Cap	✓	97	Bonnet	Good	98	Fuel Cap	✓	
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	67	AC Operation	✓	81	Boot/Tail Gate	Good	99	Mud Flaps	✓		
17	Speedo	✓	45	Rear Brakes	✓	68	Heater Fan	✓	82	Front Bumper	Good	100	WOF	✓		
18	Odometer	✓	46	Handbrake	✓	69	Seatbelts	✓	83	Rear Bumper	Good					
19	Rev Counter	✓	Keys and Locking		70	Horn	✓	84	Rear Wiper Blade	Good						
20	Fuel Gauge	✓	47	Central Locking	✓	71	Seat Heaters	•	85	R/H Mirror	Good					
21	Wipers Front/Rear	✓	48	Remote Locking	✓	72	Sun Visors	✓	86	L/H Mirror	Good					
22	Window Opener FL	✓	49	Number of Keys	2	73	Sun Visors Lights/Mirrors	✓	87	L/F Guard	Good					
23	Window Opener FR	✓	Engine		74	Seats	Good	88	R/F Guard	Good						
24	Window Opener RL	✓	50	Oil Level	✓	75	Carpets	Good	89	L/H Doors	Good					
25	Window Opener RR	✓	51	Smokes and Fumes	✓	76	Panels	Good	90	R/H Doors	Good					
26	Rear View Mirrors	•	52	Performance	✓	77	Dashboard	Good	91	L/H Sill	Good					
27	Radio (Basic Test Only)	✓	53	Noise	✓				92	R/H Sill	Good					
28	CD (Basic Test Only)	✓	54	Starter Motor	✓				93	Boot/Tail Gate	Good					
29	Boot Open Switch	✓							94	Front Bumper	Good					

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Bobby Zhong	Date:	26 Aug 2019
I have read and understood this condition guide:			
Name:		Signature:	