

Basic Vehicle Condition Guide

Report ID: 19,787,256

Pass

Version:

Engine

Created: 20 Sep 2019


Fail

N/A

Make: Model: Subaru Impreza **Body Style:** Hatchback Year: 2008 Registration: KPZ642 Reg Expiry: 10 Nov 2019 WoF Expiry: **Odometer:** 06 Aug 2020 147,870 Kms **Good No:** 19787256 VIN: 7AT0GF09X16025080 Next Service: 157184 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front screen.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Brian Hill

Evidence of Cam Belt Replacement: Yes Kms: 190,000

Engine		1	
Oil level	~		
Smoke & fumes	~		
Performance	\ \ \		
Noise	~		
Cooling System			
Coolant condition	'		
Performance	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Radiator / Hoses (visual)	'		
Transmission		I	I
Operation	/		
Noise	V		
Clutch			~
CV joints	✓		
Wheel bearings	./		
Brakes			<u> </u>
Performance	.,		
	/		
Hand Brake			·e/
Tyres (lowest observed tread			
Left front		.0	mm
Right front		.0	mm
Left rear	4	.0	mm
Right rear	4	.0	mm
Spare		Yes	
Suspension			
Suspension performance	/		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	'		
Indicators			
Dashboard warning lights	✓ ✓		
Wipers (front & rear)			
Window winder FL	V		
Window winder FR			
Window winder RL	\(\times \)		
Window winder RR	<i>y</i>		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	<i>v</i>		
Number of keys	2		
Central locking			
Remote locking	~		<u> </u>
Sat. Nav. (basic test only)			_
Reversing camera			~

I have read and understood this condition guide.

Name:			

27 Aug 2019

Date: