

## **Basic Vehicle Condition Guide**

Report ID: 19,787,468

Version: 2

**Engine** 

Created: 26 Aug 2019


Fail

N/A

Make: Model: Mazda Roadster **Body Style:** Convertible Year: 1998 Registration: **DYY673** Reg Expiry: 24 Oct 2019 WoF Expiry: **Odometer:** 22 Sep 2019 66,253 Kms **Good No:** 19787468 VIN: 7A8C12Y0707103615 **Next Service:** 73000 km **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

<u>Under Carriage & Under Bonnet Inspection Comments</u>

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

## **General Comments**

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Kms: 52,353

Oil level	~		
Smoke & fumes	~		
Performance	v v		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	!	•
Operation	~		
Noise	~		
Clutch	\( \times \) \( \t		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	8	3	mm
Right front	8	3	mm
Left rear	7		mm
Right rear	7		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	<i>V</i>		
Shock absorbers	>		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	<b>V</b>		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			•
Reversing camera			1

Signature: .....

Inspected by: Eddie Marsters Date: 26 Aug 2019

Name: .....