

Report ID: 19,787,729 Version: 1 27 Aug 2019 Created:

Make:	Toyota	Model:	Kluger	Body Style:	Wagon		Pass	Fail	N/A
Year:	2004	Registration:	HGM814	Reg Expiry:	24 Dec 2019	Engine			L
WoF Expiry:	11 Sep 2019	Odometer:	247,819 Kms	Good No:	19787729	Oil level	~		
VIN:	7AT0H642X13159956	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I		1 B d 1	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	D	-0	S S		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent				The	BID SW	Operation	~		
R = rust PT = paint def				\prod	JHIH	Noise	~		
C = crack					SC W	Clutch	•		~
P = pin dent	HIC					CV joints	~		
* = decals	SRSC 916			- AL	ELP SDW	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W S D S D S D W S D						Performance	~		
		Note: son	ne defects & blemishes		laved in the diagram	Hand Brake	~		
	pection Comments			indy not be disp				oftyre))
Left wing mirror indicator cracked and cover alignment Front tyres inner and outer edge wear						Tyres (lowest observed tread depth of tyres) Left front 1 mm			
Right rear tyre inner edge wear							1		mm
						Right front	2		mm
						Left rear	5		mm
Conditions During Body Inspection: Wet						Right rear			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Engine oil le	-	meemspeede	<u>Comments</u>			Suspension			1
Engine on i	eak					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
rins						Electrical / Accessories			
Seats	1103					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
Concert						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		
Inspected by: John Lindsay Date: 27 Aug 2019									
Date. 27 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: