

Report ID: 19,790,100 Version: 5 26 Sep 2019 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2014	Registration:	HRN100	Reg Expiry:	03 Nov 2019	Engine		-	
WoF Expiry:		Odometer:	159,017 Kms	Good No:	19790100	Oil level	~		
VIN:	MMACNKB40FD01479	Next Service:		Service History	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and the	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	s sc w sc	-0	SPW SDW	SC		Radiator / Hoses (visual)	~		
S = scratch	RE	A U			To a	Transmission	-		
D = dent	- HE			TIN		Operation	~		
R = rust PT = paint def				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+	S D SC	Clutch	~		
P = pin dent	HID				74114	CV joints	~		
* = decals	616			-Jul-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs S SC SC		P W S W			Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	1 2S)
Rear plastic guards damaged. Detachable tow bar.									mm
Chipped screen.						Right front	6.		mm
						Left rear	5.	-	mm
Conditions During Body Inspection: Dry					Right rear		4.0 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
OK, dirty.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1 1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Dirty, stain	is. drivers seat be	elt fraying.			Head lights	~		
	Dirty.					Tail lights	~		
Carpets						Indicators	~		
Panels	Dirty, scuff	fs.				Dashboard warning lights	~		
	Dirty.					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
4x4 flat dec	k Triton.					Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
	• • • •		·			Remote locking	~		
-	ming Mechanism:	Cambel				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspecte	d by: Daryll Timms					Date: 03 Sep 20	10		
						Date. 05 5ep 20	. ,		

I have read and understood this condition guide.

Name:

Signature: