

|  |  |                         | Air Conditioning / Heater   |        |   |   |
|--|--|-------------------------|-----------------------------|--------|---|---|
|  | -  |                         | Operation                   | ~      |   |   |
| -                                      | nterior Comments                                       |                         | Electrical / Accessories    |        |   |   |
|  | Seats  | Good                    | Head lights                 | ~      |   |   |
| ŀ                                      | Carpets  | Good                    | Tail lights                 | ~      |   |   |
|  |  |                         | Indicators                  | ~      |   |   |
|  | Panels   | Good                    | Dashboard warning lights    | ~      |   |   |
| ŀ                                      |  | Good                    | Wipers (front & rear)       | ~      |   |   |
|  | Dashboard  | Dashboard               |                             | ~      |   |   |
| General Comments                       |  |                         | Window winder FR            | ~      |   |   |
|  |  |                         | Window winder RL            | ~      |   |   |
|  | Engine oil leak top cover gasket.<br>Battery exhausted |                         | Window winder RR            | ~      |   |   |
|  |  |                         | Rear view mirrors           | ~      |   |   |
|  |  | Radio (basic test only) |                             | ~      |   |   |
|  |  |                         | CD (basic test only)        |        | ~ |   |
|  |  |                         | Number of keys              | keys 2 |   |   |
| Road Conditions During Test Drive: Wet |  |                         | Central locking             | ~      |   |   |
| Engine Timing Mechanism: Cambelt       |  |                         | Remote locking              | ~      |   |   |
|  |  |                         | Sat. Nav. (basic test only) |        |   | ~ |
|  | Evidence of Cam Belt Replacement: No Kms:              |                         | Reversing camera            |        |   | ~ |
|  | Inspected by: Eddie Marsters Date: 05 Sep 2019         |                         |                             |        |   |   |

I have read and understood this condition guide.

Name: .....

Signature: .....

N/A

V

mm

mm

mm

mm