

Report ID: 19,790,536 Version: 1 28 Aug 2019 Created:

Make:	Ford	Model:	Fiesta	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010		FJB982	Reg Expiry:	02 Jan 2020	Engine			.1
WoF Expiry:		Odometer:	95,763 Kms	Good No:	19790536	Oil level	~		
VIN:	WF0JXXGAJJAY88609	Next Service:		Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty	anation is maada	for one and miles as	Danta hava nat	heen discontined or	Noise	~		
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			_
a full mechar	ical inspection prior to	purchase and the	his can be arranged fo	or an additional o	harge.	Coolant condition	~		1
		_				Performance	~		
Key:		-0		-161-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	PT SC			100	EID S	Operation	~		1
R = rust				\prod	JHIH	Noise	~		
PT = paint def C = crack				+	S S	Clutch	~		
P = pin dent						CV joints	~		
* = decals	PSC PSC			AL.		Wheel bearings	~		
SC = stone chi	ps US	LA		JAL)		Brakes	V		
W = significant scuffs W S						Performance	~		1
		Noto: com	ne defects & blemishes						
	pection Comments				, -	Hand Brake			
Wear on decals, mainly on roof, tailgate and bonnet. Clearcoat is coming off RR guard over decal. Wear on						Tyres (lowest observed tread depth of tyres)			-
paint RF outer door handle. Stonechips on windscreen. Rust mark on bonnet. Paint damage on front bumper RHS.						Left front	4		mm
Heater fan	only working on full.					Right front		1	mm
						Left rear		1	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	-		<u>In comments</u>			Suspension			
Bad inner e	dge wear on both rear t	yres.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior (ammonts					Operation	~		
Interior Comments Good						Electrical / Accessories			
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
	_					Window winder FR	~		
General Comments						Window winder RL	~		
Plate on floor in LF and cuts in carpet as car was duel control previously. RR wheel center cap missing.						Window winder RR	~		
					Rear view mirrors	~			
Drives well.						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		•
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		1
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
						L			
Inspecte	d by: Roger King					Date: 28 Aug 20	19		

I have read and understood this condition guide.

Name:

Signature: