

Report ID: 19,792,227 Version: 1 02 Sep 2019 Created:

Make:	Holden	Model:	Rodeo 4X2	Body Style:	Utility		Pass	Fail	N/A
Year:	2006	Registration:	DCD796	Reg Expiry:	15 Sep 2019	Engine	I	1	1
WoF Expiry:		Odometer:	371,812 Kms	Good No:	19792227	Oil level	~		
VIN:	MPATFR77H5H54102(Next Service:	375000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II	D	1 B AL	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
		_				Performance	~		
Key:	S P SC	-0	S P SC S P SC		S	Radiator / Hoses (visual)	~		
S = scratch							Transmission		<u> </u>
						Operation	~		
R = rust				10	JHIK	Noise	~		
PT = paint defects C = crack				+	SC	Clutch			~
P = pin dent						CV joints	~		
* = decals	ssc 910			AL-	ELP SD	Wheel bearings	~		
SC = stone chips						Brakes	▼		
W = significant scuffs S P SC S P SC S P SC S P SC						Performance	~		
		Note: son	ne defects & blemishes	may not be disr		Hand Brake	~		
· · ·	pection Comments						•	ofture	
Small crack and stone chips in the windscreen ,LR tail light broken ,canopy has small cracks in it ,						Tyres (lowest observed tread depth of tyres)			-
						Left front		4	mm
						Right front	•		mm
						Left rear			mm
Conditions During Body Inspection: Dry						Right rear	3 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
						Suspension			
Interior bonnet has surface rust ,screw holes on LF guard interior gutter, Suspension performance						~			
						Steering performance	~		
Shock absorbers							~		
Air Conditioning / Heater									
Interior Comments								~	
Average						Electrical / Accessories			
Seats	Avelage					Head lights	~		
Carpets	Average					Tail lights	~		
		nsole has screw l				Indicators	~		
Panels	middle co	ISOle has screw i	ioles,			Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
CD (basic test only)									
						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
Remote locking								~	
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									۲
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			2
Inspected by: Donovan Matara Date: 02 Sep 2019									

I have read and understood this condition guide.

Name:

Signature: