

Basic Vehicle Condition Guide

Report ID: 19,794,048


Version: 2

Created: 17 Oct 2019

Make: Model: Mazda Verisa **Body Style:** Hatchback Year: 2004 Registration: LBF276 Reg Expiry: 04 Sep 2019 WoF Expiry: **Odometer: Good No:** 25 Oct 2019 74,843 Kms 19794048 VIN: 7AT0C103X17107816 **Next Service:** 84835 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

No underbody inspection completed

| Interior Comments | | | |
|-------------------|-------------------------------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Small marks on passenger side | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Bailey Michel 17 Oct 2019 Inspected by: Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|----------------------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | v v | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ' | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | • | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | Ġ | 9 | mm |
| Right front | 9 | .2 | mm |
| Left rear | 7.4 | | mm |
| Right rear | 6.3 | | mm |
| Spare | | Yes | |
| Suspension | • | | |
| Suspension performance | ~ | | |
| Steering performance | V V | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | V V V V V V | | |
| Wipers (front & rear) | ' | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| | | | |

Signature: