

Report ID: 19,795,609 Version: 1 12 Sep 2019 Created:

Signature:

Make:	Ford	Model:	Mustang	Body Style:] []	Pass	Fail	N/A	
Year:	1971	Registration:	HZL551	Reg Expiry:	11 Oct 2019	Engine				
WoF Expiry:	25 Dec 2019	Odometer:	98,909 Kms	Good No:	19795609	Oil level	~			
VIN:	7AT06G0FX15136331	Next Service:		Service History	/: No	Smoke & fumes		~		
					-	Performance		~		
	port is not a warranty		c			Noise		~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~		[
						Performance	~			
Key:		-0				Radiator / Hoses (visual)	~			
S = scratch	STE	10		100	T	Transmission	•			
D = dent					EIU /	Operation	~			
R = rust					HIH	Noise	~			
PT = paint defe C = crack	ect M		-	+	PT	Clutch	~		~	
P = pin dent	Ho				JUII —				<i>v</i> <i>v</i>	
* = decals	- MIR				ANR	CV joints			~	
SC = stone chips						Wheel bearings	~			
W = significant scuffs						Brakes			1	
		Note: som		pes may not be displ	layed in the diagram	Performance Hand Brake	~	~		
	pection Comments	Note: son	le delects & blemis	les may not be disp	ayed in the diagram		-	ofture		
RH door outer metal strip insecure Rear and side badges missing						Tyres (lowest observed tread depth of tyres)				
Front bumper misaligned. Front windscreen seal damages.						Left front		5	mm	
Spare wheel insecure						Right front		6 mm		
Unable to locate switches for headlamp hi low beam and wiper						Left rear	5 mm		-	
Conditions During Body Inspection: Dry						Right rear	5 mm			
Under Carriage & Under Pennet Inspection Comments					Spare Yes					
Under Carriage & Under Bonnet Inspection Comments						Suspension			1	
Battery inse Intake throt	cure tle linkages touching b	onnet while oper	ning.Petrol leak fror	n carburetor.Oil leal	ks- Engine,	Suspension performance	~			
transmissio	n, rear differential		5		J I	Steering performance		~		
Exhaust mo Rear wheel						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation		~		
	Good					Electrical / Accessories				
Seats	Good					Head lights			~	
Carpets	Good					Tail lights	~			
						Indicators	~			
Panels	Root, side	linings torn				Dashboard warning lights			~	
Dashboa	rd Good					Wipers (front & rear)			~	
						Window winder FL	~			
						Window winder FR	~			
General Comments					Window winder RL			~		
Parking brake release handle broken Engine starting difficulty, misfiring.						Window winder RR			~	
Noise while						Rear view mirrors	~			
Power steer	ring noisy while turning					Radio (basic test only)		~		
						CD (basic test only)			~	
						Number of keys	1			
Road Con	ditions During Test	t Drive:	Wet			Central locking			~	
	-					Remote locking			~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	Inspected by: Mathew Varghese Date: 12 Sep 2019									

I have read and understood this condition guide.

Name: