

Report ID: 19,796,475 Version: 3 21 Dec 2019 Created:

Make:	Hyundai	Model:	Getz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	ENR344	Reg Expiry:	22 Jul 2020	Engine			
WoF Expiry:		Odometer:	65,139 Kms	Good No:	19796475	Oil level	~		
VIN:	KMHBT51DR8U79687	Next Service:		Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		с I I		1 10 11 1	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0	LS		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	GIE			The	EID S	Operation	~		
R = rust PT = paint def				\prod	JHIH	Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		
* = decals	s sc PIK			AL.	ENPR-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inst	pection Comments	Note: 3011	le delects & blemisnes	indy not be disp	ayed in the diagram		-	ofturo	
					Tyres (lowest observed tread depth of tyres)				
						Left front	5.		mm
						Right front	6.	-	mm
						Left rear	3.		mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	-	mermspectic	<u>on comments</u>			Suspension			
Front whee	arive					Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior (ommonts					Operation	~		
Interior Comments Good						Electrical / Accessories			
Seats	duod					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	<		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	-		·			Remote locking	~		
-	ming Mechanism:	Cambel				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Greg Morgan Date: 17 Dec 2019									

I have read and understood this condition guide.

Name:

Signature: