

Report ID: 19,796,633 Version: 1 Created: 04 Sep 2019

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	Registration:	KUA487	Reg Expiry:	24 Nov 2019	Engine			·
WoF Expiry:	18 Sep 2020	Odometer:	109,602 Kms	Good No:	19796633	Oil level	~		
VIN:	7AT0GK0CX17107061	Next Service:	119381	Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty	anation is maada	for one and miles as	Dauta hava nat	hoon dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	S P	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	scw 6/6			The	HID W	Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint defe C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	PSC PIC			AL.	EIIR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: com	ne defects & blemishes		layed in the diagram	Hand Brake			
Body Insp	pection Comments	1016.3011	le delects & blemisnes	inay not be disp	layed in the diagram			ofturo	
					Tyres (lowest observed tread depth of tyres)				
						Left front	3.		mm
						Right front	4.		mm
						Left rear		3.0 mm	
Conditions During Body Inspection: Wet						Right rear	4.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
	inage a onder bor	meemspeede	<u>eominents</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	/ Telage					Head lights	~		
Carpets	Average					Tail lights	~		
- ·	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Concret	Comments					Window winder FR	~		ļ
						Window winder RL	~		ļ
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
L						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ning Machanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Greg Morgan Date: 04 Sep 2019									

I have read and understood this condition guide.

Name:

Signature: