

Report ID: 19,796,826 Version: 1 Created: 04 Sep 2019

Make:	Holden	Model:	Captiva 5	Body Style:	SUV		Pass	Fail	N/A
Year:	2013	Registration:	·	Reg Expiry:	10 Oct 2019	Engine			L
WoF Expiry:		Odometer:	133,741 Kms	Good No:	19796826	Oil level	~		
VIN:	KL3DA26UJCB112020	Next Service:	135000	Service Histor		Smoke & fumes	~		<u> </u>
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		SC SC			Performance	~		
Key:	La C	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	SC D			710	HIVW	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	PSC DR				7414	CV joints	~		
* = decals				To .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan			SC SC		SC	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			25)
						Left front	5.	0	mm
						Right front	5.	0	mm
						Left rear	3	8	mm
Conditions During Body Inspection: Wet						Right rear	3 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	11		L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Deall	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet Central locking									
	-					Remote locking	~		
-	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							10		
Inspected by: Chris Vanner Date: 04 Sep 2019									

I have read and understood this condition guide.

Name:

Signature: