


<b>Make:</b>	Mitsubishi	<b>Model:</b>	Diamante	<b>Body Style:</b>	Sedan
<b>Year:</b>	1996	<b>Registration:</b>	ABJ944	<b>Reg Expiry:</b>	05 Sep 2019
<b>WoF Expiry:</b>	25 Sep 2019	<b>Odometer:</b>	306,118 Kms	<b>Good No:</b>	19797139
<b>VIN:</b>	7A8CJ0N0701100519	<b>Next Service:</b>	301,000kms	<b>Service History:</b>	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key:

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



## Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Centre caps are missing off right & left side front alloy wheels. Stone chips in windscreen. Left rear mud flap is not fitting correctly. Trim panel on drivers door is coming unstuck from door.

Conditions During Body Inspection: Wet

## Under Carriage & Under Bonnet Inspection Comments

Engine sump plug washer has oil leaking from it. Oil weeping from between engine & gearbox. Starting to get underbody surface rust.

## Interior Comments

Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

## General Comments

Engine oil level is below the low mark on engine dip stick. Radiator/coolant system needs a flush. Handbrake needs adjustment. Storage pocket on right side of dashboard is not staying closed. CD player is not working. (VEHICLE LOCATED IN DUNEDIN)

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Kms: 274,287

	Pass	Fail	N/A
<b>Engine</b>			
Oil level		✓	
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition		✓	
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake		✓	
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	3.5	mm	
Right front	4.6	mm	
Left rear	5.0	mm	
Right rear	5.3	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking		✓	
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Jason Young

Date: 06 Sep 2019

I have read and understood this condition guide.

Name: .....

Signature: .....