

# **Basic Vehicle Condition Guide**

Report ID: 19,798,098


Version: 2

11 Dec 2019

Make: Model: Ford Mondeo **Body Style:** Hatchback Year: 2009 Registration: EZQ644 Reg Expiry: 10 Jan 2020 WoF Expiry: **Odometer: Good No:** 27 May 2020 240,412 Kms 19798098 VIN: WF0EXXGBBE8Y83876 Next Service: 252,000 Service History:

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



# **Body Inspection Comments**

FR door bottom seal insecure

Rear bumper misaligned. LH tail lamp broken Power window master switch not working properly

Rear wiper washer not working

**Conditions During Body Inspection:** Wet

### **Under Carriage & Under Bonnet Inspection Comments**

Excessive engine oil leak Front wheel drive

Interior Comments					
Seats	Good				
Carpets	Average				
Panels	Average				
Dashboard	Good				

## **General Comments**

**Engine** noisy AC airflow low

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement:

I have read and understood this condition guide.

Kms.

Name: .....

vidence of cam belt heplacement.		NO INITIS.		Reversing came	g camera	
Inspected by:	Jason Law			Date:	11 Dec 201	9

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance	V V	Fail	N/A
Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance	<i>V</i>	·	
Smoke & fumes Performance Noise Cooling System Coolant condition Performance	ν ν	V	
Performance Noise  Cooling System Coolant condition Performance	<b>'</b>	<b>v</b>	
Noise  Cooling System  Coolant condition  Performance		~	
Cooling System  Coolant condition  Performance			
Coolant condition Performance		~	
Performance			
	•		
	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			•
Performance	<b>'</b>		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	s)
Left front	3	3	mm
Right front	3	 }	mm
Left rear	1		mm
Right rear	3	3	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		<b>/</b>	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Window winder RL	~		
Window winder RR	<b>v</b>		
Rear view mirrors	~		
Radio (basic test only)	<b>'</b>		
CD (basic test only)	<b>V</b>		
Number of keys	1		
Central locking	<b>v</b>		
Remote locking	·		
Sat. Nav. (basic test only)			_
Reversing camera			~
Date: 11 Dec 201			

Signature: .....