

## **Basic Vehicle Condition Guide**

Report ID: 19,802,215


Version: 2

Created: 13 Sep 2019

Make: Model: RIO KIA **Body Style:** Hatchback Year: 2018 Registration: LKU877 Reg Expiry: 31 Jan 2020 WoF Expiry: **Odometer: Good No:** 29 Jun 2021 6,633 Kms 19802215 VIN: **Next Service:** KNADB514LJ6190857 Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

## **General Comments**

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Eddie Marsters Date: 13 Sep 2019

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	<i>V V</i>			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	>			
Noise	\( \times \)			
Clutch	~			
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front		7	mm	
Right front	7.5		mm	
Left rear	8		mm	
Right rear	8		mm	
Spare		Yes		
Suspension		ı		
Suspension performance	~			
Steering performance	<i>V</i>			
Shock absorbers	•			
Air Conditioning / Heater				
Operation	-			
Electrical / Accessories				
Head lights	-			
Tail lights Indicators	•			
	-			
Dashboard warning lights	-			
Wipers (front & rear)	-			
Window winder FL Window winder FR	V V V V V V V		-	
Window winder FR Window winder RL				
Window winder RE Window winder RR	•			
Rear view mirrors	•		$\vdash$	
Radio (basic test only)  CD (basic test only)	<i>'</i>		.,	
Number of keys	2			
Central locking	4			
Remote locking	<i>y</i>			
Sat. Nav. (basic test only)			V	
Reversing camera	~			
L.c. crossing cumera				

I have read and understood this condition guide.

Name: .....

Signature: .....